DAILY WORK ORDER	
Work Site: Bossert Manufacturing	Work Period: 7/09/87
Contractor: O. H. Materials Contractor Rep.: Paul Street	OSC: Jack D. Harmon
Work Planned/Authorized: 1)Complete the removal of paper from area #1 - 2nd floor	Work Accomplished From Previous Work Order:
 2) Initiate the removal of steel from sumps & stockpile for disposal 3) Mercury vac area #7 and verify absence of mercury vapors 4) Initiate sampling area #3 5) Continue removal and stockpiling wood shelving in area #13 	2.) (x) () () 3.) (x) () () 4.) () (x)
EQUIPMENT PLANNED/AUTHORIZED: Port. Eyewash Mini-Trackhoe Water Treatment System w/ appurtenand Decon Trailer (3) 12K & (1) 50K pool (2)Office/Break Trailer (3) Vans (1) Car (1) Pick-up truck (3) Bobcats Scaffolding (2) Satellites 6CY Dumpster (2) 6.5KW Generators 955 Loader (3) Hilti guns (12) Air cylinders (1) Aerial Lift; (1) Pneumatic Forkl: (20) Propane tanks Hi-P water lasers	All Authorized COMMENTS: Mobilize HEPA vac and mercury vapor
(2) Laborer(1)(1) Lab Technician (2)(2)	Foreman (Level 3) Foreman (Level 2) Field Clerk Clean-up Technician (Level 2) Operator (Level 2)
Contractor Signature: Date: 7/9/87	OSC Signature: Osc Signature: Osc Signature: Osc Signature: Osc Signature: